

XRAY 808

INSTRUCTION MANUAL SUPPLEMENTARY SHEET

In case that servo is touching the chassis side guard, use appropriate shims to ensure there is small play.

10. RADIO CASE **PAGE 29 / STEP 1**

SH M3x14

SH M3x8

SFH M3x8

Play

Use appropriate shims to ensure there is space between chassis side guard and servo.

E	D	C
2.5mm	1.5mm	1mm

If you have any questions, please do not hesitate to contact XRAY at info@teamxray.com or visit our website at www.teamxray.com for news and updates.